

RDA REPORT

Villagio
Queen Creek, Arizona
Account 3610 - Version 001
September 14, 2012

RESERVE DATA ANALYSIS, INC.

2761 East Bridgeport Parkway
Gilbert, Arizona 85295
FAX (480) 473-7658
(480) 473-7643

Prepared By

KARL THOMPSON

RDA Reserve Management Software
Copyright 2012, Edwin G. Edgley
All Rights Reserved

Please Note

This document has been provided pursuant to an agreement containing restrictions on its use. No part of this document may be copied or distributed, in any form or by any means, nor disclosed to third parties without the express written permission of Reserve Data Analysis, Inc., until it has been paid for in full. The Client shall have the right to reproduce and distribute copies of this report, or the information contained within, as may be required for compliance with all applicable regulations.

This reserve analysis study and the parameters under which it has been completed are based upon information provided to us in part by representatives of the association, its contractors, assorted vendors, specialist and independent contractors, the Community Associations Institute, various construction pricing and scheduling manuals including, but not limited to: Marshall & Swift Valuation Service, RS Means Facilities Maintenance & Repair Cost Data, RS Means Repair & Remodeling Cost Data, National Construction Estimator, National Repair & Remodel Estimator, Dodge Cost Manual and the McGraw Hill Book Company. Additionally, costs are obtained from numerous vendor catalogues, actual quotations or historical costs, and our own experience in the field of property management and preparation of reserve analysis studies.

It has been assumed, unless otherwise noted in this report, that all assets have been designed and constructed properly and each estimated useful life will approximate that of the norm per industry standards and/or manufacture specifications used. In some cases, estimates may have been used on assets which have an indeterminable but potential liability to the association. The decision for the inclusion of these as well as all assets considered is left to the client.

We recommend that your reserve analysis study be updated every two to three years due to fluctuating interest rates, inflationary changes and the unpredictable nature of the lives of many of the assets under consideration. All of the information collected during our inspection of the association and subsequent computations made in preparing this reserve analysis study are retained in our computer files. Therefore, updates can typically be completed in a more timely manner than the original study.

Reserve Data Analysis, Inc. would like to thank you for using our services, and we invite you to call us at any time should you have any questions or comments or need assistance. In addition, any of the parameters and estimates used in this study may be changed at your request, after which we will provide you with a revised study.

RESERVE DATA ANALYSIS, INC.

(480) 473-7643

TABLE OF CONTENTS

PART I - INTRODUCTION

THE RESERVE BUDGET

Funding Options	1-1
The Reserve Study	1-2
Developing a Component List	1-3
Preparing the Reserve Study	1-4
Funding Methods	1-5
Funding Strategies	1-5
Distribution of Accumulated Reserves	1-7
Funding Reserves	1-8

USING YOUR RESERVE ANALYSIS STUDY

User's Guide to Your Reserve Analysis Study	1-9
Definitions	1-10
A Multi-Purpose Tool	1-13

PART II - RESERVE ANALYSIS STUDY

Cash Flow Specific Summary of Calculations	2-1
Distribution of Accumulated Reserves	2-2
Cash Flow Specific Projections	2-3
Annual Expenditure Detail	2-4
Cash Flow Detail Report by Category	2-8
Detail Report Index	2-23

PART I - INTRODUCTION

Preparing the annual budget and overseeing the association's finances are perhaps the most important responsibilities of board members. The annual operating and reserve budgets reflect the planning and goals of the association and set the level and quality of service for all of the association's activities.

■ 1. Funding Options

When a major repair or replacement is required in a community, an association has essentially four options available to address the expenditure:

The first option is to pass a "special assessment" to the membership in an amount required to cover the expenditure. Although not commonplace, there have been special assessments in the amount of \$10,000 per member assessed in associations in Virginia and southern California. When a special assessment is passed, the association has the authority and responsibility to collect the assessments, even by means of foreclosure if necessary. However, an association operating on a special assessment basis cannot guarantee that an assessment, when needed, will be passed. Consequently, it cannot guarantee its ability to perform the required repairs or replacements to those major components for which the association is obligated to maintain when the need arises. Additionally, while relatively new communities require very little in the way of major "reserve" expenditures, associations reaching 12 to 15 years of age and older find many components reaching the end of their effective useful lives. These required expenditures, all accruing at the same time, can be devastating to an association's overall budget.

The second option is for the association to acquire a loan from a lending institution in order to effect the required repairs. In many cases, banks will lend money to an association using "future homeowner assessments" as collateral for the loan. With this method, not only is the current board of directors pledging the future assets of an association, they are also required to pay interest fees on the loan payback in addition to the original principal. In the case of a \$150,000 roofing replacement, the association may be required to pay back the loan over a three to five year period, with interest; whereas, if the association was setting aside reserves for this purpose, using the

vehicle of the regularly assessed membership dues, it would have had the full term of the life of the roof in order to accumulate the necessary moneys. Additionally, those contributions would have been evenly distributed over the entire membership and would have earned interest as part of that contribution.

The third option, too often used, is simply to defer the required repair or replacement. This option can create an environment of declining property values due to the increasing deferred maintenance and the association's financial inability to keep pace with the normal aging process of the common area components. This, in turn, can have a seriously negative impact on sellers in the Association by making it difficult or even impossible for potential buyers to obtain financing from lenders. Increasingly, many lending institutions are requesting copies of the association's most recent reserve study before granting loans, either for the association, a prospective purchaser, or for an individual within such association.

The fourth, and only logical means that the board of directors has to ensure its ability to maintain the assets for which it is obligated, uniformly distributing the costs of the replacements over the entire membership, is by assessing an adequate level of reserves as part of the regular membership assessment. The community is not only comprised of present members, but also future members. Any decision by the board of directors to adopt a calculation method or funding plan which would disproportionately burden future members in order to make up for past reserve deficits would be a breach of its fiduciary responsibility to those future members. Unlike individuals determining their own course of action, the board is responsible to the "community" as a whole.

■ 2. The Reserve Study

There are two components of a reserve study – a physical analysis and a financial analysis. During the physical analysis, a reserve provider evaluates information regarding the physical status and repair/replacement cost of the association's major common area components. To do so, the provider conducts a component inventory, a condition assessment, and life and valuation estimates. A financial analysis assesses the association's reserve balance or "fund status" (measured in cash or as percent funded) to determine a recommendation for an appropriate reserve contribution rate in the future known as the "funding plan."

Reserve studies fit into one of three categories: 1) Full Study; 2) Update - with site inspection; and 3) Update - without site inspection.

- In a Full reserve study, the reserve provider conducts a component inventory, a condition assessment (based upon on-site visual observations), and life and valuation estimates to determine both a "fund status" and "funding plan."

- In an Update – with site inspection, the reserve provider conducts a component inventory (verification only, not quantification), a condition assessment (based on on-site visual observations), and life and valuation estimates to determine both the “fund status” and “funding plan.”
- In an Update – without site inspection, the reserve provider conducts life and valuation estimates to determine the “fund status” and “funding plan.”

■ 3. Developing a Component List

The budget process begins with an accurate inventory of all the major components for which the association is responsible. The determination of whether an expense should be labeled as operational, reserve, or excluded altogether is sometimes subjective. Since this labeling may have a major impact on the financial plans of the association, subjective determinations should be minimized. We suggest the following considerations when labeling an expense:

OPERATIONAL EXPENSES occur at least annually, no matter how large the expense, and can be effectively budgeted for each year. They are characterized as being reasonably predictable both in terms of frequency and cost. Operational expenses include all minor expenses which would not otherwise adversely affect an operational budget from one year to the next. Examples of Operational Expenses include:

Utilities:

- Electricity
- Gas
- Water
- Telephone
- Cable TV

Services:

- Landscaping
- Pool Maintenance
- Street Sweeping
- Accounting
- Reserve Study

Administrative:

- Supplies
- Bank Service Charges
- Dues & Publications
- Licenses, Permits & Fees

Repair Expenses:

- Tile Roof Repairs
- Equipment Repairs
- Minor Concrete Repairs
- Operating Contingency

RESERVE EXPENSES are major expenses that occur other than annually and which must be budgeted for in advance in order to provide the necessary funds in time

for their occurrence. Reserve expenses are reasonably predictable both in terms of frequency and cost. However, they may include significant assets which have an indeterminable but potential liability which may be demonstrated as a likely occurrence. They are expenses that when incurred would have a significant affect on the smooth operation of the budgetary process from one year to the next if they were not reserved for in advance. Examples of Reserve Expenses include:

- Roof Replacements
- Painting
- Deck Resurfacing
- Fencing Replacement
- Street Seal/Slurry Coatings
- Asphalt Overlays
- Pool Re-plastering
- Pool Equipment Replacement
- Pool Furniture Replacement
- Tennis Court Resurfacing
- Park & Play Equipment
- Equipment Replacement
- Interior Furnishings
- Lighting Replacement

BUDGETING IS NORMALLY EXCLUDED FOR repairs or replacements of assets which are deemed to have an estimated useful life equal to or exceeding the estimated useful life of the facility or community itself, or exceeding the legal life of the community as defined in an association's governing documents. Examples include the complete replacement of elevators, tile roofs, wiring and plumbing. Also excluded are insignificant expenses which may be covered either by an operating or reserve contingency, or otherwise in a general maintenance fund. Costs which are caused by acts of God, accidents or other occurrences which are more properly insured for, rather than reserved for, are also excluded.

■ 4. Preparing the Reserve Study

Once the reserve assets have been identified and quantified, their respective replacement costs, useful lives and remaining lives must be assigned so that a funding schedule can be constructed. Replacement costs and useful lives can be found in published manuals such as construction estimators, appraisal handbooks, and valuation guides. Remaining lives are calculated from the useful lives and ages of assets and adjusted according to conditions such as design, manufacture quality, usage, exposure to the elements and maintenance history.

By following the recommendations of an effective reserve study the association should avoid any major shortfalls. However, to remain accurate, the report should be updated every two to three years to reflect such changes as shifts in economic parameters, additions of phases or assets, or expenditures of reserve funds. The association can assist in simplifying the reserve analysis update process by keeping accurate records of these changes throughout the year.

■ 5. Funding Methods

From the simplest to most complex, reserve analysis providers use many different computational processes to calculate reserve requirements. However, there are two basic processes identified as industry standards: the cash-flow method and the component method.

The cash flow method develops a reserve-funding plan where contributions to the reserve fund are designed to offset the variable annual expenditures from the reserve fund. Different reserve funding plans are tested against the actual anticipated schedule of reserve expenses until the desired funding goal is achieved. This method sets up a "window" in which all future anticipated replacement costs are computed, based on the individual lives of the components under consideration.

The component method develops a reserve-funding plan where the total contribution is based on the sum of contributions for individual components. The component method is the more conservative of the two funding options, and assures that the association will achieve and maintain an ideal level of reserves over time. This method also allows for computations on individual components in the analysis. The RDA Summary and RDA Projection Reports are based upon the component methodology.

■ 6. Funding Strategies

Once an association has established its funding goals, the association can select an appropriate funding plan. There are two basic strategies widely used by associations. It is recommended that associations consult professionals to determine the best strategy or combination of plans that best suit the association's need. Additionally, associations should consult with their financial advisor to determine the tax implications of selecting a particular plan. Further, consultation with the American Institute of Certified Public Accountants (AICPA) for their reporting requirements is advisable. The two funding plans and descriptions of both are detailed below.

- Full Funding — Given that the basis of funding for reserves is to distribute the costs of the replacements over the lives of the components in question, it follows that the ideal level of reserves would be proportionately related to those lives and costs. If an association has a component with an expected estimated useful life of ten years, it would set aside approximately one-tenth of the replacement cost each year. At the end of three years, one would expect that three-tenths of the replacement cost to have accumulated, and if so, that component would be "fully-funded." This model is

important in that it is a measure of the adequacy of an association's reserves at any one point of time, and is independent of any particular method which may have been used for past funding or may be under consideration for future funding. The formula is based on current replacement cost, and is a measure in time, independent of future inflationary or investment factors:

$$\text{Fully Funded Reserves} = \frac{\text{Age of Component}}{\text{Useful Life}} \times \text{Current Replacement Cost}$$

When an association's total accumulated reserves for all components meet this criteria, its reserves are "fully-funded."

- **Threshold Funding (RDA Modified Cash Flow Reports)** — There are two goals of this funding method. The first goal is to make sure that all scheduled reserve expenditures are covered by keeping the reserve cash balance above zero during the projected period. The second goal is to reach and maintain a 100% fully funded reserve balance during the projected period. Depending on the association's current percent funded, it may take the entire projected period (typically 30 years) before the 100% fully funded level is achieved.

Reaching and maintaining a 100% fully funded reserve balance by uniformly distributing the costs of the replacements over time benefits both current and future members of an association, and is the best approach the board of directors can take to fulfill its fiduciary responsibility. The modified cash flow method creates a funding strategy that gives the membership the lowest reserve funding recommendation as possible over time, while approaching the 100% fully funded level.

Another advantage of the modified cash flow method is that in most cases several strategies can be manually tested by Reserve Data Analysis, Inc. (the strategy is not based strictly on each component's current funding status) until the best funding strategy is created – one that has consistent, incremental contribution increases from year to year. This very important aspect of the reserve study will aid the board of directors during the annual budgeting process.

■ 7. Distribution of Accumulated Reserves

The first step is to identify the ideal level of reserves for each asset. As indicated in the prior section, this is accomplished by evaluating the component's age proportionate to its estimated useful life and current replacement cost. Again, the equation used is as follows:

$$\text{Fully Funded Reserves} = \frac{\text{Age of Component}}{\text{Useful Life}} \times \text{Current Replacement Cost}$$

The RDA RESERVE MANAGEMENT SOFTWARE™ program performs the above calculations to the very month the component was placed-in-service. It also allows for the accumulation of the necessary reserves for the replacement to be available on the first day of the fiscal year it is scheduled to be replaced.

After identifying the ideal level of reserves for each asset, the beginning reserve balance must be allocated to each of the individual components identified in the analysis.

The next step the program performs is to arrange all of the assets used in the study in ascending order by remaining life, and alphabetically within each grouping of remaining life items. These assets are then assigned their respective ideal level of reserves until the amount of funds available are depleted, or until all assets are appropriately funded. If any assets are assigned a zero remaining life (schedule for replacement this fiscal year), then the amount assigned equals the current replacement cost and funding begins for the next cycle of replacement. If there are insufficient funds available to accomplish this, then the software automatically adjusts the zero remaining life item to 1 year and that asset assumes its new grouping position alphabetically in the final printed report.

If at the completion of this task there are additional moneys which have not been distributed, the remaining reserves are then assigned, in ascending order, to a level equal to, but not exceeding, the current replacement cost for each component. If there are sufficient moneys available to fund all assets at their current replacement cost levels, then any excess funds are designated as such initially, but are then considered to be available reserves in the report funding computations.

Assigning the reserves in this manner defers the make-up period for any underfunding over the longest remaining life of all the assets under consideration, thereby minimizing the impact of deficiency. For example, if the report indicates an underfunding of \$50,000, this underfunding will be assigned to components with the longest remaining life possible in order to give more time to "replenish" the account. If the \$50,000 underfunding were to be assigned to short remaining life items, the impact would be immediately felt.

If the reserves are underfunded, the monthly contribution requirements as outlined in this report may be higher than normal depending on the calculation method that is used. In future years, as individual assets are replaced, the funding requirements will return to their normal levels. In the case of a large deficiency, a special assessment may be considered. The program can easily generate revised reports outlining how the monthly contributions would be affected by such an adjustment, or by any other changes which may be under consideration.

■ 8. Funding Reserves

Two contribution numbers are provided in the report, the "Monthly Membership Contribution" and the "Net Monthly Allocation." The association should contribute to reserves each month the "Monthly Membership Contribution" figure, when the interest earned on the reserves is left in the reserve accounts as part of the contribution. When interest is earned on the reserves, that interest must be left in reserves and only amounts set aside for taxes should be removed.

The second alternative is to allocate the "Net Monthly Allocation" to reserves (this is the member contribution plus the anticipated interest earned for the fiscal year). This method assumes that all interest earned will be assigned directly as operating income. This allocation takes into consideration the anticipated interest earned on accumulated reserves regardless of whether or not it is actually earned. When taxes are paid the amount due will be taken directly from the association's operating accounts as the reserve accounts are allocated only those moneys net of taxes.

■ 9. Users' Guide to Your Reserve Analysis Study

Part II of your RDA REPORT contains the reserve analysis study for your association. There are seven types of pages in the study as described below.

REPORT SUMMARY

The **Report Summary** lists all of the parameters which were used in calculating the report as well as the summary of your reserve analysis study.

INDEX REPORTS

The **Distribution of Accumulated Reserves** report lists all assets in remaining life order. It also identifies the ideal level of reserves which should have accumulated for the association as well as the actual reserves available.

DETAIL REPORTS

The **Detail Report** itemizes each asset and lists all measurements, current and future costs and calculations for that asset. Provisions for percentage replacements, salvage values and one-time replacements can also be utilized.

The numerical listings for each asset are enhanced by extensive narrative detailing factors such as design, manufacture quality, usage, exposure to elements and maintenance history.

The **Detail Report Index** is an alphabetical listing of all assets together with the page number of the asset's detail report and asset number.

PROJECTIONS AND CHARTS

Thirty-year Projections of projected data add to the usefulness of your reserve analysis study.

■ 10. Definitions

REPORT I.D. - Includes the REPORT DATE (ex. November 15, 1992), VERSION (ex. 001), and ACCOUNT NUMBER (ex. 9773). Please use this information when referencing your report. (Displayed on the summary page.)

BUDGET YEAR BEGINNING/ENDING - The budgetary year for which the report is prepared. For associations with fiscal years ending December 31, the monthly contribution figures indicated are for the 12 month period beginning 1/1/2X and ending 12/31/2X.

NUMBER OF UNITS/PHASES - If applicable, the number of units and/or phases included in this version of the report.

INFLATION - This figure is used to approximate the future cost to repair or replace each component in the report. The current cost for each component is compounded on an annual basis by the number of remaining years to replacement and the total is used in calculating the monthly reserve contribution which will be necessary in order to accumulate the required funds in time for replacement.

ANNUAL CONTRIBUTION INCREASE - The percentage rate at which the association will increase its contribution to reserves at the end of each year until the year in which the asset is replaced. For example, in order to accumulate \$10,000 in 10 years, you could set aside \$1,000 per year. As an alternative, you could set aside \$795 the first year and increase that amount by 5% each year until the year of replacement. In either case you arrive at the same amount. The idea is that you start setting aside a lower amount and increase that number each year in accordance with the planned percentage. Ideally this figure should be equal to the rate of inflation. It can, however, be used to aid those associations that have not set aside appropriate reserves in the past by making the initial year's allocation less formidable.

INVESTMENT YIELD - The average interest rate anticipated by the association based upon its current investment practices.

TAXES ON YIELD - The estimated percentage of interest income which will be set aside for taxes.

ACCUMULATED RESERVE BALANCE - The anticipated reserve balance on the first day of the fiscal year for which this report has been prepared. Based upon information provided and not audited.

PERCENT FULLY FUNDED - The ratio, at the beginning of the fiscal year, of the actual (or projected) reserve balance to the calculated fully funded balance, expressed as a percentage.

PHASE INCREMENT DETAIL/AGE - Comments regarding aging of the components on the basis of construction date or date of acceptance by the association.

MONTHLY CONTRIBUTION - The contribution to reserves required by the association each month.

INTEREST CONTRIBUTION - The interest that should be earned on the reserves, net of taxes, based upon their beginning reserve balance and monthly contributions for one year. This figure is averaged for budgeting purposes.

NET MONTHLY ALLOCATION - The sum of the monthly contribution and interest contribution figures.

GROUP OR FACILITY NUMBER/CATEGORY NUMBER - The report may be prepared and sorted either by group or facility (location, building, phase, etc.) or by category (roofing, painting, etc.). Standard report printing format is by category.

PERCENTAGE OF REPLACEMENT - In some cases, an asset may not be replaced in its entirety or the cost may be shared with a second party. Examples are budgeting for a percentage of replacement of streets over a period of time, or sharing the expense to replace a common wall with a neighboring party.

PLACED-IN-SERVICE - The month and year that the asset was placed-in-service. - This may be the construction date, the first escrow closure date in a given phase, or the date of the last servicing or replacement.

ESTIMATED USEFUL LIFE - The estimated useful life of an asset based upon industry standards, manufacturer specifications, visual inspection, location, usage, association standards and prior history. All of these factors are taken into consideration when tailoring the estimated useful life to the particular asset. For example, the carpeting in a hallway or elevator (a heavy traffic area) will not have the same life as the identical carpeting in a seldom-used meeting room or office.

ADJUSTMENT TO USEFUL LIFE - Once the useful life is determined it may be adjusted +/- by this separate figure for the current cycle of replacement. This will allow for a current period adjustment without affecting the estimated replacement cycles for future replacements.

ESTIMATED REMAINING LIFE - This calculation is completed internally based upon the report's fiscal year date and the date the asset was placed-in-service.

REPLACEMENT YEAR - The year that the asset is scheduled to be replaced. The appropriate funds will be available by the first day of the fiscal year for which replacement is anticipated.

FIXED ACCUMULATED RESERVES - An optional figure which, if used, will override the normal process of allocating reserves to each asset.

FIXED MONTHLY CONTRIBUTION - An optional figure which, if used, will override all calculations and set the contribution at this amount.

SALVAGE VALUE - The salvage value of the asset at the time of replacement, if applicable.

ONE-TIME REPLACEMENT - Notation if the asset is to be replaced on a one-time basis.

CURRENT REPLACEMENT COST - The estimated replacement cost effective as of the beginning of the fiscal year for which the report is being prepared.

FUTURE REPLACEMENT COST - The estimated cost to repair or replace the asset at the end of its estimated useful life based upon the current replacement cost and inflation.

COMPONENT INVENTORY - The task of selecting and quantifying reserve components. This task can be accomplished through on-site visual observations, review of association design and organizational documents, a review of established association precedents and discussion with appropriate association representative(s).

■ 11. A Multi-Purpose Tool

Your RDA REPORT is an important part of your association's budgetary process. Following its recommendations should ensure the association's smooth budgetary transitions from one fiscal year to the next, and either decrease or eliminate the need for "special assessments".

In addition, your RDA reserve study serves a variety of useful purposes:

- Following the recommendations of a reserve study performed by a professional consultant can protect the Board of Directors in a community from personal liability concerning reserve components and reserve funding.
- A reserve analysis study is required by your accountant during the preparation of the association's annual audit.
- A reserve study is often requested by lending institutions during the process of loan applications, both for the community and, in many cases, the individual owners.
- Your RDA REPORT is also a detailed inventory of the association's major assets and serves as a management tool for scheduling, coordinating and planning future repairs and replacements.
- Your RDA REPORT is a tool which can assist the Board in fulfilling its legal and fiduciary obligations for maintaining the community in a state of good repair. If a community is operating on a special assessment basis, it cannot guarantee that an assessment, when needed, will be passed. Therefore, it cannot guarantee its ability to perform the required repairs or replacements to those major components which the association is obligated to maintain.
- Since the RDA reserve analysis study includes precise measurements and cost estimates of the client's assets, the detail reports may be used to evaluate the accuracy and price of contractor bids when assets are due to be repaired or replaced.
- The reserve study is an annual disclosure to the membership concerning the financial condition of the association, and may be used as a "consumers' guide" by prospective purchasers.

© Copyright 2001, Edwin G. Edgley
All Rights Reserved

Villagio
 Queen Creek, Arizona
CFS Reserve Analysis Report Summary

Report Date	September 14, 2012	Parameters:	
Version	001	Inflation	3.00%
Account Number	3610	Annual Contribution Increase	3.00%
Budget Year Beginning	1/ 1/13	Investment Yield	0.50%
Ending	12/31/13	Taxes on Yield	0.00%
Total Units Included	135	Contingency	3.00%
Phase Development	1 of 1	Reserve Fund Balance as of	
		1/ 1/13:	\$0.00

Project Profile & Introduction

The client has advised us to use January 2013 as the basis for aging the components examined in this analysis.

All inventories and measurements were obtained from information and/or plans provided by the client.

Calculation Method: Modified Cash Flow
 Funding Strategy: Threshold
 RDA Reports: September 2012 (from plans).

Cash Flow Specific Summary of Calculations

Monthly Contribution to Reserves Required:	\$1,529.00
(\$11.33 per unit per month)	
Average Net Monthly Interest Contribution This Year:	3.51
Net Monthly Allocation to Reserves 1/ 1/13 to 12/31/13:	\$1,532.51
(\$11.35 per unit per month)	

RDA Reserve Management Software
 Copyright 2012, Edwin G. Edgley
 All Rights Reserved

Villagio
Distribution of Accumulated Reserves

REPORT DATE: September 14, 2012
 VERSION: 001
 ACCOUNT NUMBER: 3610

DESCRIPTION	REM LIFE	FULLY FUNDED RESERVES	ASSIGNED RESERVES
Concrete Components - Unfunded	0	0.00	0.00
Irrigation System - Unfunded	0	0.00	0.00
Roofs - Metal, Ramadas, Unfunded	0	0.00	0.00
Tree Trimming - Unfunded	0	0.00	0.00
Paint - Wrought Iron (50%)	4	0.00	0.00
Drywells - Repair & Clean Out	5	0.00	0.00
Sand Replenishment (Lot 83)	5	0.00	0.00
Paint - Block Walls	8	0.00	0.00
Paint - Ramada Supports (Lot 83)	8	0.00	0.00
Paint - Ramada Supports (Soccer)	8	0.00	0.00
Sail Shade Fabric (South Walkway)	12	0.00	0.00
Shade Structure Fabric (Lot 83)	12	0.00	0.00
Tot Turf (Lot 83)	12	0.00	0.00
Granite Replenishment	15	0.00	0.00
Irrigation Controllers	15	0.00	0.00
Park Equipment (Lot 83)	16	0.00	0.00
Park Equipment (Soccer Field)	16	0.00	0.00
Park Equipment (South Walkway)	16	0.00	0.00
Exercise Course (South Walkway)	20	0.00	0.00
Mailboxes - Pedestal Sets	20	0.00	0.00
Monument Signs - Letters	20	0.00	0.00
Playstructure (Lot 83)	20	0.00	0.00
Fencing - Wrought Iron (50%)	30	0.00	0.00
Total Asset Summary:		0.00	0.00
Contingency @ 3.00%:		0.00	0.00
Grand Total:		0.00	0.00
Excess Reserves Not Used:			0.00

Villagio
Cash Flow Specific Projections

REPORT DATE: September 14, 2012
 VERSION: 001
 ACCOUNT NUMBER: 3610

Beginning Accumulated Reserves: \$0

YEAR	CURRENT REPLACEMENT COST	ANNUAL CONTRBTN	ANNUAL INTEREST CONTRBTN	ANNUAL EXPENDTRS	PROJECTED ENDING RESERVES	FULLY FUNDED RESERVES	PERCENT FULLY FUNDED
'13	223,030	18,348	42	0	18,390	16,037	115%
'14	229,721	18,898	136	0	37,424	33,037	113%
'15	236,613	19,465	232	0	57,122	51,042	112%
'16	243,711	20,049	332	0	77,503	70,098	111%
'17	251,022	20,651	421	2,983	95,592	87,087	110%
'18	258,553	21,270	493	6,927	110,429	100,942	109%
'19	266,309	21,908	604	0	132,941	123,120	108%
'20	274,299	22,566	718	0	156,225	146,538	107%
'21	282,528	23,243	765	14,251	165,982	156,130	106%
'22	291,004	23,940	887	0	190,808	181,739	105%
'23	299,734	24,658	973	8,030	208,409	200,225	104%
'24	308,726	25,398	1,103	0	234,910	228,432	103%
'25	317,987	26,160	1,134	20,602	241,601	236,293	102%
'26	327,527	26,945	1,273	0	269,819	266,933	101%
'27	337,353	27,753	1,416	0	298,988	299,199	100%
'28	347,473	28,586	732	166,087	162,218	156,959	103%
'29	357,898	29,443	703	35,424	156,940	149,822	105%
'30	368,635	30,326	856	0	188,122	180,824	104%
'31	379,694	31,236	1,014	0	220,373	213,551	103%
'32	391,084	32,173	1,178	0	253,725	248,079	102%
'33	402,817	33,139	692	130,880	156,675	145,636	108%
'34	414,902	34,133	864	0	191,671	179,839	107%
'35	427,349	35,157	1,041	0	227,869	215,964	106%
'36	440,169	36,211	1,225	0	265,306	254,094	104%
'37	453,374	37,298	1,180	46,856	256,928	244,608	105%
'38	466,975	38,417	1,313	12,510	284,147	272,252	104%
'39	480,985	39,569	1,515	0	325,231	315,006	103%
'40	495,414	40,756	1,723	0	367,711	360,079	102%
'41	510,277	41,979	1,909	6,063	405,535	401,142	101%
'42	525,585	43,238	2,132	0	450,905	450,969	100%

Villagio
Annual Expenditure Detail

REPORT DATE: September 14, 2012
VERSION: 001
ACCOUNT NUMBER: 3610

DESCRIPTION	EXPENDITURES
REPLACEMENT YEAR 2013	
*** ANNUAL TOTAL:	0.00
REPLACEMENT YEAR 2014	
*** ANNUAL TOTAL:	0.00
REPLACEMENT YEAR 2015	
*** ANNUAL TOTAL:	0.00
REPLACEMENT YEAR 2016	
*** ANNUAL TOTAL:	0.00
REPLACEMENT YEAR 2017	
Paint - Wrought Iron (50%)	2,982.60
*** ANNUAL TOTAL:	<hr/> 2,982.60
REPLACEMENT YEAR 2018	
Drywells - Repair & Clean Out	4,695.07
Sand Replenishment (Lot 83)	2,231.61
*** ANNUAL TOTAL:	<hr/> 6,926.68
REPLACEMENT YEAR 2019	
*** ANNUAL TOTAL:	0.00
REPLACEMENT YEAR 2020	
*** ANNUAL TOTAL:	0.00
REPLACEMENT YEAR 2021	
Paint - Block Walls	9,880.81
Paint - Ramada Supports (Lot 83)	506.71
Paint - Ramada Supports (Soccer)	506.71
Paint - Wrought Iron (50%)	3,356.95
*** ANNUAL TOTAL:	<hr/> 14,251.18

Villagio
Annual Expenditure Detail

DESCRIPTION	EXPENDITURES
REPLACEMENT YEAR 2022	
*** ANNUAL TOTAL:	0.00
REPLACEMENT YEAR 2023	
Drywells - Repair & Clean Out	5,442.87
Sand Replenishment (Lot 83)	2,587.06
*** ANNUAL TOTAL:	8,029.93
REPLACEMENT YEAR 2024	
*** ANNUAL TOTAL:	0.00
REPLACEMENT YEAR 2025	
Paint - Wrought Iron (50%)	3,778.28
Sail Shade Fabric (South Walkway)	4,277.28
Shade Structure Fabric (Lot 83)	3,421.82
Tot Turf (Lot 83)	9,124.87
*** ANNUAL TOTAL:	20,602.25
REPLACEMENT YEAR 2026	
*** ANNUAL TOTAL:	0.00
REPLACEMENT YEAR 2027	
*** ANNUAL TOTAL:	0.00
REPLACEMENT YEAR 2028	
Drywells - Repair & Clean Out	6,309.78
Granite Replenishment	150,079.01
Irrigation Controllers	6,699.26
Sand Replenishment (Lot 83)	2,999.11
*** ANNUAL TOTAL:	166,087.16
REPLACEMENT YEAR 2029	
Paint - Block Walls	12,516.72
Paint - Ramada Supports (Lot 83)	641.89
Paint - Ramada Supports (Soccer)	641.89
Paint - Wrought Iron (50%)	4,252.49
Park Equipment (Lot 83)	6,338.59
Park Equipment (Soccer Field)	5,375.78
Park Equipment (South Walkway)	5,656.58

Villagio
Annual Expenditure Detail

DESCRIPTION	EXPENDITURES
*** ANNUAL TOTAL:	35,423.94
REPLACEMENT YEAR 2030	
*** ANNUAL TOTAL:	0.00
REPLACEMENT YEAR 2031	
*** ANNUAL TOTAL:	0.00
REPLACEMENT YEAR 2032	
*** ANNUAL TOTAL:	0.00
REPLACEMENT YEAR 2033	
Drywells - Repair & Clean Out	7,314.76
Exercise Course (South Walkway)	14,159.90
Mailboxes - Pedestal Sets	26,008.02
Monument Signs - Letters	2,889.76
Paint - Wrought Iron (50%)	4,786.20
Playstructure (Lot 83)	72,244.45
Sand Replenishment (Lot 83)	3,476.79
*** ANNUAL TOTAL:	130,879.88
REPLACEMENT YEAR 2034	
*** ANNUAL TOTAL:	0.00
REPLACEMENT YEAR 2035	
*** ANNUAL TOTAL:	0.00
REPLACEMENT YEAR 2036	
*** ANNUAL TOTAL:	0.00
REPLACEMENT YEAR 2037	
Paint - Block Walls	15,855.81
Paint - Ramada Supports (Lot 83)	813.11
Paint - Ramada Supports (Soccer)	813.11
Paint - Wrought Iron (50%)	5,386.91
Sail Shade Fabric (South Walkway)	6,098.39
Shade Structure Fabric (Lot 83)	4,878.68
Tot Turf (Lot 83)	13,009.89

Villagio
Annual Expenditure Detail

DESCRIPTION	EXPENDITURES
*** ANNUAL TOTAL:	<hr/> 46,855.90
REPLACEMENT YEAR 2038	
Drywells - Repair & Clean Out	8,479.81
Sand Replenishment (Lot 83)	4,030.55
*** ANNUAL TOTAL:	<hr/> 12,510.36
REPLACEMENT YEAR 2039	
*** ANNUAL TOTAL:	0.00
REPLACEMENT YEAR 2040	
*** ANNUAL TOTAL:	0.00
REPLACEMENT YEAR 2041	
Paint - Wrought Iron (50%)	6,063.02
*** ANNUAL TOTAL:	<hr/> 6,063.02
REPLACEMENT YEAR 2042	
*** ANNUAL TOTAL:	0.00

Villagio
Cash Flow Detail Report by Category

REPORT DATE: September 14, 2012
 VERSION: 001
 ACCOUNT NUMBER: 3610

Concrete Components - Unfunded

ASSET ID 1001
 GROUP/FACILITY 0
 CATEGORY 10

QUANTITY	1 comment
UNIT COST	0.000
PERCENT REPL	0.00%
CURRENT COST	0.00
FUTURE COST	0.00
SALVAGE VALUE	0.00

PLACED IN SERVICE 0/ 0
 0 YEAR USEFUL LIFE
 +0 YEAR ADJUSTMENT
 REPLACEMENT YEAR 2013
 0 YEAR REM LIFE

REMARKS:

We are not budgeting for repair or replacement of concrete decks, pads, sidewalks, or driveways as a reserve component. It is anticipated that any repairs required will be addressed immediately due to safety concerns. Good maintenance practice won't allow the need for repairs to accumulate to a point of major expense. We recommend that the client includes a line item in the annual operating budget for repairs and/or replacements on an "as needed" basis. However, should the client wish to include budgeting for concrete components, we will do so at their request (cost and useful life to be provided by client).

Villagio
Cash Flow Detail Report by Category

Roofs - Metal, Ramadas, Unfunded

ASSET ID 1020
 GROUP/FACILITY 0
 CATEGORY 20

 PLACED IN SERVICE 0/ 0
 0 YEAR USEFUL LIFE
 +0 YEAR ADJUSTMENT
 REPLACEMENT YEAR 2013
 0 YEAR REM LIFE

QUANTITY	1 comment
UNIT COST	0.000
PERCENT REPL	0.00%
CURRENT COST	0.00
FUTURE COST	0.00
SALVAGE VALUE	0.00

REMARKS:

We are not budgeting to replace the metal ramada roof(s) because they have an indefinite life, and should last for the life of the community if properly maintained. Any repairs should be handled on an "as needed" basis, and the expense paid for out of the operating budget.

Villagio
Cash Flow Detail Report by Category

Paint - Block Walls		QUANTITY	26,000 sq. ft.
		UNIT COST	0.300
ASSET ID	1009	PERCENT REPL	100.00%
GROUP/FACILITY	0	CURRENT COST	7,800.00
CATEGORY	30	FUTURE COST	9,880.81
		SALVAGE VALUE	0.00
PLACED IN SERVICE	1/13		
8 YEAR USEFUL LIFE			
+0 YEAR ADJUSTMENT			
REPLACEMENT YEAR	2021		
8 YEAR REM LIFE			

REMARKS:

This component is to paint the perimeter and interior common area block walls. The cost includes an estimate for prep, repairs and painting.

Paint - Ramada Supports (Lot 83)		QUANTITY	1 ramada
		UNIT COST	400.000
ASSET ID	1022	PERCENT REPL	100.00%
GROUP/FACILITY	0	CURRENT COST	400.00
CATEGORY	30	FUTURE COST	506.71
		SALVAGE VALUE	0.00
PLACED IN SERVICE	1/13		
8 YEAR USEFUL LIFE			
+0 YEAR ADJUSTMENT			
REPLACEMENT YEAR	2021		
8 YEAR REM LIFE			

REMARKS:

This component is to paint the metal ramada support structures.
 Location: play area next to Lot 83

Paint - Ramada Supports (Soccer)		QUANTITY	1 ramada
		UNIT COST	400.000
ASSET ID	1021	PERCENT REPL	100.00%
GROUP/FACILITY	0	CURRENT COST	400.00
CATEGORY	30	FUTURE COST	506.71
		SALVAGE VALUE	0.00
PLACED IN SERVICE	1/13		
8 YEAR USEFUL LIFE			
+0 YEAR ADJUSTMENT			
REPLACEMENT YEAR	2021		
8 YEAR REM LIFE			

Villagio
Cash Flow Detail Report by Category

Paint - Ramada Supports (Soccer), Continued ...

REMARKS:

This component is to paint the metal ramada support structures.

Location: next to the soccer field

Paint - Wrought Iron (50%)

QUANTITY	5,300 sq. ft.
UNIT COST	1.000
PERCENT REPL	50.00%
CURRENT COST	2,650.00
FUTURE COST	2,982.60
SALVAGE VALUE	0.00

ASSET ID 1010
 GROUP/FACILITY 0
 CATEGORY 30

PLACED IN SERVICE 1/13
 4 YEAR USEFUL LIFE
 +0 YEAR ADJUSTMENT
 REPLACEMENT YEAR 2017
 4 YEAR REM LIFE

REMARKS:

This component is to paint the wrought iron fencing located on boundary lines between lots and common area.

The cost to maintain this fencing is to be shared on a 50% - 50% basis between the Association and the individual lot owners. See page 20, Section 4.3.24.2, of the CC&Rs for an explanation of the maintenance responsibilities.

Villagio
Cash Flow Detail Report by Category

Fencing - Wrought Iron (50%)

ASSET ID 1012
 GROUP/FACILITY 0
 CATEGORY 40

 PLACED IN SERVICE 1/13
 30 YEAR USEFUL LIFE
 +0 YEAR ADJUSTMENT
 REPLACEMENT YEAR 2043
 30 YEAR REM LIFE

QUANTITY	1 total
UNIT COST	37,420.000
PERCENT REPL	50.00%
CURRENT COST	18,710.00
FUTURE COST	45,414.08
SALVAGE VALUE	0.00

REMARKS:

330 - lin. ft. of 2'0" fencing	@	\$ 22.00	=	\$ 7,260.00
1,160 - lin. ft. of 4'0" fencing	@	26.00	=	30,160.00

		TOTAL	=	\$ 37,420.00

This component is to replace the wrought iron fencing located on boundary lines between lots and common area.

The cost to maintain this fencing is to be shared on a 50% - 50% basis between the Association and the individual lot owners. See page 20, Section 4.3.24.2, of the CC&Rs for an explanation of the maintenance responsibilities.

Villagio
Cash Flow Detail Report by Category

Park Equipment (Lot 83)		QUANTITY	1 total
ASSET ID	1015	UNIT COST	3,950.000
GROUP/FACILITY	0	PERCENT REPL	100.00%
CATEGORY	65	CURRENT COST	3,950.00
		FUTURE COST	6,338.59
		SALVAGE VALUE	0.00
PLACED IN SERVICE	1/13		
16 YEAR USEFUL LIFE			
+0 YEAR ADJUSTMENT			
REPLACEMENT YEAR	2029		
16 YEAR REM LIFE			

REMARKS:

1 - 6' picnic table	@	\$ 1,000.00	=	\$ 1,000.00
3 - 6' benches	@	600.00	=	1,800.00
2 - trash receptacles w/lids	@	575.00	=	1,150.00

		TOTAL	=	\$ 3,950.00

The costs include an estimate for installation.

Location: playstructure play area next to Lot 83

Playstructure (Lot 83)		QUANTITY	1 total
ASSET ID	1016	UNIT COST	40,000.000
GROUP/FACILITY	0	PERCENT REPL	100.00%
CATEGORY	65	CURRENT COST	40,000.00
		FUTURE COST	72,244.45
		SALVAGE VALUE	0.00
PLACED IN SERVICE	1/13		
20 YEAR USEFUL LIFE			
+0 YEAR ADJUSTMENT			
REPLACEMENT YEAR	2033		
20 YEAR REM LIFE			

REMARKS:

This component is to replace the Little Tikes playstructure and spring mates.

Location: play area next to Lot 83

We are not budgeting to replace the steel framed swing set because it has an indefinite life. Any rubber seat or chain replacements should be handled on an "as needed" basis out of the operating budget.

Villagio
Cash Flow Detail Report by Category

Sand Replenishment (Lot 83)		QUANTITY	1 total
ASSET ID	1024	UNIT COST	1,925.000
GROUP/FACILITY	0	PERCENT REPL	100.00%
CATEGORY	65	CURRENT COST	1,925.00
		FUTURE COST	2,231.60
		SALVAGE VALUE	0.00
PLACED IN SERVICE	1/13		
5 YEAR USEFUL LIFE			
+0 YEAR ADJUSTMENT			
REPLACEMENT YEAR	2018		
5 YEAR REM LIFE			

REMARKS:

The client has requested that we budget \$1,925 to replenish the sand at the playstructure play area every five years (2,750 sq. ft.).

Location: play area next to Lot 83

Shade Structure Fabric (Lot 83)		QUANTITY	800 sq. ft.
ASSET ID	1018	UNIT COST	3.000
GROUP/FACILITY	0	PERCENT REPL	100.00%
CATEGORY	65	CURRENT COST	2,400.00
		FUTURE COST	3,421.83
		SALVAGE VALUE	0.00
PLACED IN SERVICE	1/13		
12 YEAR USEFUL LIFE			
+0 YEAR ADJUSTMENT			
REPLACEMENT YEAR	2025		
12 YEAR REM LIFE			

REMARKS:

This component is to replace the shade structure fabric (hip & ridge) located above the playstructure.

Location: play area next to Lot 83

Villagio
Cash Flow Detail Report by Category

Tot Turf (Lot 83)

ASSET ID 1017
GROUP/FACILITY 0
CATEGORY 65

QUANTITY	400 sq. ft.
UNIT COST	16.000
PERCENT REPL	100.00%
CURRENT COST	6,400.00
FUTURE COST	9,124.87
SALVAGE VALUE	0.00

PLACED IN SERVICE 1/13
12 YEAR USEFUL LIFE
+0 YEAR ADJUSTMENT
REPLACEMENT YEAR 2025
12 YEAR REM LIFE

REMARKS:

This component is to replace the Tot Turf at the playstructure play area.

Location: play area next to Lot 83

Villagio
Cash Flow Detail Report by Category

Park Equipment (Soccer Field)		QUANTITY	1 total
		UNIT COST	3,350.000
ASSET ID	1013	PERCENT REPL	100.00%
GROUP/FACILITY	0	CURRENT COST	3,350.00
CATEGORY	66	FUTURE COST	5,375.77
		SALVAGE VALUE	0.00
PLACED IN SERVICE	1/13		
16 YEAR USEFUL LIFE			
+0 YEAR ADJUSTMENT			
REPLACEMENT YEAR	2029		
16 YEAR REM LIFE			

REMARKS:

1 - 6' picnic table	@	\$ 1,000.00	=	\$ 1,000.00
2 - 6' benches	@	600.00	=	1,200.00
2 - trash receptacles w/lids	@	575.00	=	1,150.00

		TOTAL	=	\$ 3,350.00

The costs include an estimate for installation.

Location: next to the soccer field

Villagio
Cash Flow Detail Report by Category

Exercise Course (South Walkway)		QUANTITY	1 total
		UNIT COST	7,840.000
ASSET ID	1023	PERCENT REPL	100.00%
GROUP/FACILITY	0	CURRENT COST	7,840.00
CATEGORY	67	FUTURE COST	14,159.91
		SALVAGE VALUE	0.00
PLACED IN SERVICE 1/13			
20 YEAR USEFUL LIFE			
+0 YEAR ADJUSTMENT			
REPLACEMENT YEAR 2033			
20 YEAR REM LIFE			

REMARKS:

There are 8 par stations (exercise stations) located along the south walkway. The client has advised us to budget \$7,840, every 20 years, for the replacement of the equipment at the eight stations.

Park Equipment (South Walkway)		QUANTITY	1 total
		UNIT COST	3,525.000
ASSET ID	1014	PERCENT REPL	100.00%
GROUP/FACILITY	0	CURRENT COST	3,525.00
CATEGORY	67	FUTURE COST	5,656.59
		SALVAGE VALUE	0.00
PLACED IN SERVICE 1/13			
16 YEAR USEFUL LIFE			
+0 YEAR ADJUSTMENT			
REPLACEMENT YEAR 2029			
16 YEAR REM LIFE			

REMARKS:

3 - 6' benches	@	\$ 600.00	=	\$ 1,800.00
3 - trash receptacles w/lids	@	575.00	=	1,725.00

		TOTAL	=	\$ 3,525.00

The costs include an estimate for installation.

Location: under the sail shades along the south walkway

Villagio
Cash Flow Detail Report by Category

Sail Shade Fabric (South Walkway)

ASSET ID 1019
GROUP/FACILITY 0
CATEGORY 67

PLACED IN SERVICE 1/13
12 YEAR USEFUL LIFE
+0 YEAR ADJUSTMENT
REPLACEMENT YEAR 2025
12 YEAR REM LIFE

QUANTITY	1 total
UNIT COST	3,000.000
PERCENT REPL	100.00%
CURRENT COST	3,000.00
FUTURE COST	4,277.28
SALVAGE VALUE	0.00

REMARKS:

This component includes a provision to replace the fabric portions of the three sail shades (144 sq. ft. each).

Location: along the south walkway

Villagio
Cash Flow Detail Report by Category

Drywells - Repair & Clean Out

ASSET ID 1008
 GROUP/FACILITY 0
 CATEGORY 100

 PLACED IN SERVICE 1/13
 5 YEAR USEFUL LIFE
 +0 YEAR ADJUSTMENT
 REPLACEMENT YEAR 2018
 5 YEAR REM LIFE

QUANTITY	3 drywells
UNIT COST	1,350.000
PERCENT REPL	100.00%
CURRENT COST	4,050.00
FUTURE COST	4,695.06
SALVAGE VALUE	0.00

REMARKS:

These are MaxWell Plus system drywells in the community water retention tracts.

Drywell systems should be inspected annually to determine how much debris has accumulated in the system and to develop a clean out schedule. Some drywell systems will require the immediate repair of broken components and clean out, while others won't require maintenance for a number of years. On average, drywell systems require clean out every 3 - 5 years. A drywell should be cleaned out once 10% or more of the chamber is occupied. If maintained properly, drywells are designed to last as long as any other part of the community infrastructure.

A great majority of the drywell systems in Arizona are installed by Torrent Resources. Torrent Resources has developed a maintenance program to aid communities with drywell maintenance. Their comprehensive three year maintenance program waives the annual inspection fee, provides a 25% discount on replacement parts & site drainage modifications, and provides a detailed inspection report indicating the location and status of each drywell.

Given that no current maintenance program for your community's drywells is known to RDA, we have included a provision to repair and clean out the drywells. It is likely that the clean out schedule will vary over time, and, therefore, the cost should be considered as a general indication of budgetary needs.

We recommend contacting Jeremy Livengood (602.268.0785) with Torrent Resources to obtain additional information about drywells and/or to set up your community's maintenance program. The maintenance and clean out recommendations provided by Torrent Resources can then be incorporated into a revision or future update of this report.

Villagio
Cash Flow Detail Report by Category

Granite Replenishment

ASSET ID 1002
 GROUP/FACILITY 0
 CATEGORY 100

 PLACED IN SERVICE 1/13
 15 YEAR USEFUL LIFE
 +0 YEAR ADJUSTMENT
 REPLACEMENT YEAR 2028
 15 YEAR REM LIFE

QUANTITY	1 total
UNIT COST	96,330.000
PERCENT REPL	100.00%
CURRENT COST	96,330.00
FUTURE COST	150,079.00
SALVAGE VALUE	0.00

REMARKS:

The client has advised us to budget in the following manner for granite replenishment in the common areas and along the DG trail:

Common Area: \$90,288 every 15 years (376,000 sq. ft.)

DG Trail: \$6,042 every 15 years (14,050 sq. ft.)

Therefore, the total current cost for granite replenishment is \$96,330.

Irrigation Controllers

ASSET ID 1005
 GROUP/FACILITY 0
 CATEGORY 100

 PLACED IN SERVICE 1/13
 15 YEAR USEFUL LIFE
 +0 YEAR ADJUSTMENT
 REPLACEMENT YEAR 2028
 15 YEAR REM LIFE

QUANTITY	1 total
UNIT COST	4,300.000
PERCENT REPL	100.00%
CURRENT COST	4,300.00
FUTURE COST	6,699.26
SALVAGE VALUE	0.00

REMARKS:

1	- Irritrol MC-E, 20 station	@	\$ 1,000.00	=	\$ 1,000.00
2	- Irritrol MC-E, 24 station	@	1,000.00	=	2,000.00
1	- Irritrol MC-E, 30 station	@	1,300.00	=	1,300.00

TOTAL					= \$ 4,300.00

The costs include an estimate for installation.

Villagio
Cash Flow Detail Report by Category

Irrigation System - Unfunded

ASSET ID 1004
 GROUP/FACILITY 0
 CATEGORY 100

 PLACED IN SERVICE 0/ 0
 0 YEAR USEFUL LIFE
 +0 YEAR ADJUSTMENT
 REPLACEMENT YEAR 2013
 0 YEAR REM LIFE

QUANTITY	1	comment
UNIT COST	0.000	
PERCENT REPL	0.00%	
CURRENT COST	0.00	
FUTURE COST	0.00	
SALVAGE VALUE	0.00	

REMARKS:

We have been advised that irrigation systems (pvc piping, sprinkler heads, valves, etc.) have a useful life of approximately 20 years, and should be included as a reserve component. However, budgeting for the replacement of the irrigation system requires evaluating the present condition (remaining useful life) and replacement cost - both of which call for expert evaluation, but fall outside the scope of a reserve study. Therefore, we recommend that the client have the system evaluated to determine these two factors so that budgeting can be included in a revision or future update of this report.

Mailboxes - Pedestal Sets

ASSET ID 1006
 GROUP/FACILITY 0
 CATEGORY 100

 PLACED IN SERVICE 1/13
 20 YEAR USEFUL LIFE
 +0 YEAR ADJUSTMENT
 REPLACEMENT YEAR 2033
 20 YEAR REM LIFE

QUANTITY	1	total
UNIT COST	14,400.000	
PERCENT REPL	100.00%	
CURRENT COST	14,400.00	
FUTURE COST	26,008.00	
SALVAGE VALUE	0.00	

REMARKS:

9 - 16 box sets w/2 parcel lockers @ \$ 1,600.00 = \$ 14,400.00

 TOTAL = \$ 14,400.00

We are projecting that there will be pedestal mounted mailbox units throughout the community. The exact number and type of units was not available at the time of this analysis. We have provided an estimate based upon the number of units at the community. The exact inventory can be obtained at the time of a future update to this report.

Villagio
Cash Flow Detail Report by Category

Monument Signs - Letters

ASSET ID 1007
 GROUP/FACILITY 0
 CATEGORY 100

 PLACED IN SERVICE 1/13
 20 YEAR USEFUL LIFE
 +0 YEAR ADJUSTMENT
 REPLACEMENT YEAR 2033
 20 YEAR REM LIFE

QUANTITY	1 total
UNIT COST	1,600.000
PERCENT REPL	100.00%
CURRENT COST	1,600.00
FUTURE COST	2,889.78
SALVAGE VALUE	0.00

REMARKS:

This component is to replace the pin mounted letters making up the two monument signs that indicate "VILLAGIO".

Tree Trimming - Unfunded

ASSET ID 1003
 GROUP/FACILITY 0
 CATEGORY 100

 PLACED IN SERVICE 0/ 0
 0 YEAR USEFUL LIFE
 +0 YEAR ADJUSTMENT
 REPLACEMENT YEAR 2013
 0 YEAR REM LIFE

QUANTITY	1 comment
UNIT COST	0.000
PERCENT REPL	0.00%
CURRENT COST	0.00
FUTURE COST	0.00
SALVAGE VALUE	0.00

REMARKS:

We have been advised that major tree trimming is usually required every 3 - 5 years and could be considered as a reserve component. However, the cost for such a project depends on the size, type, maturity, and number of trees at the community - all of which call for expert evaluation, but fall outside the scope of a reserve study. Should the client obtain a cost and schedule we will include budgeting for this component in a revision or future update of this report at their request.

DETAIL REPORT INDEX

ASSET	DESCRIPTION	PAGE
1001	Concrete Components - Unfunded	2-8
1008	Drywells - Repair & Clean Out	2-19
1023	Exercise Course (South Walkway)	2-17
1012	Fencing - Wrought Iron (50%)	2-12
1002	Granite Replenishment	2-20
1005	Irrigation Controllers	2-20
1004	Irrigation System - Unfunded	2-21
1006	Mailboxes - Pedestal Sets	2-21
1007	Monument Signs - Letters	2-22
1009	Paint - Block Walls	2-10
1022	Paint - Ramada Supports (Lot 83)	2-10
1021	Paint - Ramada Supports (Soccer)	2-10
1010	Paint - Wrought Iron (50%)	2-11
1015	Park Equipment (Lot 83)	2-13
1013	Park Equipment (Soccer Field)	2-16
1014	Park Equipment (South Walkway)	2-17
1016	Playstructure (Lot 83)	2-13
1020	Roofs - Metal, Ramadas, Unfunded	2-9
1019	Sail Shade Fabric (South Walkway)	2-18
1024	Sand Replenishment (Lot 83)	2-14
1018	Shade Structure Fabric (Lot 83)	2-14
1017	Tot Turf (Lot 83)	2-15
1003	Tree Trimming - Unfunded	2-22

TOTAL ASSET LINES INCLUDED: 23